U31MR RAID setting SOP

Professional I/O adapter provider

Bplus Technology Co., Ltd.

Roger Tseng

Bplus Technology Co., Ltd.

2015/12/15

roger@bplus.com.tw

U31MR

Dual mSATA SSD RAID to USB 3.1 Type C

U31MR

Dual mSATA SSD RAID to USB 3.1 Type C

Catalog

RAID setting Step

Step 1: Insert 2 SATA SSD to U31MR，see the picture as below:

Step 2: Connect USB type C cable to USB port of system (laptop or desktop)，see the picture as below:

Step 3: Connect power cable and USB type C cable to U31MR, see the picture as below:

Step 4: Setting RAID Mode, see the picture as below:

Step 5: Setting RAID Reset，Short J4 5 sec (need connector to system), see the picture as below:

Step 6: System will be refresh HDD list again: